

Dolan Chemical Laboratory 4001 Bixby Road Groveport, OH 43125 T: 614-836-4221, Audinet 210-4221 F: 614-836-4168, Audinet 210-4168 http://aepenv/labs

Water Analysis

Location: Mountaineer Plant

R	eno	rt D	ate: '	10	13/2	012
		""	aic.	ľ	J/ Z	

CPS Effluent								
Sample Number: 124155-001			Date Collected:		09/24/2012 08:00		Date Received: 9/26/2012	
Parameter		Result	Units	RL	MDL	Analysis By	Analysis Date/Time	Method
Bromide, Br		43.5	mg/L	5	1	KLG	10/03/2012 14:00	EPA 300.1
Selenium, Se		394	ug/L	0.5	0.1	DPC	10/01/2012 15:02	EPA 200.8
Chloride, Cl		3750	mg/L	20	5	KLG	10/03/2012 13:33	EPA 300.1
Fluoride, F		60.3	mg/L	1	0.2	KLG	10/03/2012 14:00	EPA 300.1

CPS Effluent								
Sample Number: 124155-002			Date Collected:		09/26/2012 08:00		Date Received: 9/26/2012	
Parameter		Result	Units	RL	MDL	Analysis By	Analysis Date/Time	Method
Bromide, Br		35.8	mg/L	5	1	KLG	10/03/2012 14:39	EPA 300.1
Selenium, Se		381	ug/L	0.5	0.1	DPC	10/01/2012 15:07	EPA 200.8
Chloride, Cl		3270	mg/L	20	5	KLG	10/03/2012 14:18	EPA 300.1
Fluoride, F		55.5	mg/L	1	0.2	KLG	10/03/2012 14:39	EPA 300.1

Brian Snyder, Chemist II

Email bssnyder@aep.com Tel. 614-836-4224
Fax 614-836-4168 Audinet 210-4224

THIS TEST REPORT RELATES ONLY TO THE ITEMS TESTED AND SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT WRITTEN APPROVAL OF THE LABORATORY. ALL TEST RESULTS MEET ALL OF THE REQUIREMENTS OF THE ACCREDITING AUTHORITY, UNLESS OTHERWISE NOTED.